MATERIAL SAFETY DATA SHEET

● Section 1 - PRODUCT IDENT	IFICATION	V				
MANUFACTURER'S NAME DEARBORN CHEMICAL CO., Subsidiary, W. R. Grace & Co.					EMERGENCY PHONE NO	
300 Genesee St., Lake	Zurich,	IL 60047				
CHEMICAL NAME AND SYNONYMS Boiler water treatme	ent			TRADE	NAME OR CODE I DEARBORN® 81	
• Section 2 – INGREDIENTS	CAS No. %		%	EXPOSURE CRITERIA		
			 	<u></u>		
	- HAZARDOUS MATERIAL uct identified in this Data Sheet					
					•	
		a hazardous				. "
ļ		of Title 29,			-	
1	Regulatio	ns 1915, <mark>19</mark>	16, 1917			
•		······································			NFPA Cod	le: 0-0-0
 Section 3 — PHYSICAL DATA 	1					
BOILING POINT, 760mm Hg		N/A	MELTIN	G POINT		N/K
ECIFIC GRAVITY (H ₂ 0 = 1)	density	11.2 lbs/ga	1,VAPOR	PRESSURE		N/A
VAPOR DENSITY (AIR = 1)		N/A	SOLUBII	_ITY IN H₂O, % BY	WT.	appreciable
% VOLATILES BY VOLUME		N/A	EVAPOR	RATION RATE,	= 1	N/A
APPEARANCE AND ODOR White	crystall	ine powder	pH of	1% solution		6.8
 Section 4 – FIRE AND EXPL 	OSION HA	ZARD DATA				
FLASH POINT (and Method Used)		ELAMANA DI ELIMITS IN ALD VIDILINAE ALITO IGNITION TEMP				N TEMPERATURE
]	None	LOWEI	R N/A	UPPER N/A	N/A	
EXTINGUISHING MEDIA	Foam CO ₂ Dry Chemic		eal Other			
SPECIAL FIRE FIGHTING PROCEDU			None			
			0,0110			-
UNUSUAL FIRE AND EXPLOSION F	IAZARD			· · · · · · · · · · · · · · · · · · ·		
			No	ne		
		,		·		
• Section 5 — REACTIVITY DA						
STABILITY (Normal Conditions) CONDITIONS TO AVOID None				<i>4</i>		
⊠ Stable ☐ Unstable				Holle		
INCOMPATIBILITY (Materials to Avo	id)	None		,		
<u>.</u>		None	•	•		
YZARDOUS DECOMPOSITION PRO	DDUCTS					
		None			•	
HAZARDOUS POLYMERIZATION	CONDI	TIONS TO AVO	ID			
☐ May Occur ☐ ☑ Will Not Occu	İ	,,,,,,,,,,		None		-
	<u> </u>				(ove	
					COVE	> L J

Section 6 - HEALTH HAZARD I		
	1 LD ₅₀ (mouse) >	7 g/kg
Modele 014	± 2250 (mode) /	7 51 25
EFFECTS OF OVEREXPOSURE		
INDALATION		
Avoid inhala	tion of powder wi	which may irritate nasal passages.
INGESTION If ingested, dri	nk large amount	of milk or water to neutralize.
		throat. If discomfort persists, consult a
physician.		
CKIN OD EVE CONTACT. TE. 1		
with soap and water. Flush	ict contacts skin eves with clear	n or clothing, remove loose dust and wash
•	•	
EMERGENCY AND FIRST AID PROCEDU	JRES	
	See above	ve
	•	
•		
• Section 7 - SPECIAL PROTECTION	ON INFORMATION	N
VENTILATION REQUIREMENTS	Mechanical exhaus	ust is adequate.
•	· · · · · · · · · · · · · · · · · · ·	
RESPIRATORY PROTECTION (Specify Ty	ype) 71 1	
or equal has been suggested	ose adequate	te respirator for dusting - 3M #8710 respirator
EYE PROTECTION		GLOVES (Specify Type)
Goggles		None
OTHER PROTECTIVE CLOTHING AND E	QUIPMENT (Specify Ty	Type) None
•		
Section 8 SPILL OR LEAK PRO	CEDURES	
STEPS TO BE TAKEN IF MATERIAL IS R		ED Sweep up and return to container for use.
	d contaminated pr	product as noted under Disposal instructions
below. WASTE DISPOSAL METHOD		
Disp	ose using chemica	cal scavenger service in auth. landfill.
This is not an EPA Hazardous W	aste.	your state water pollution control agency.
• Section 9 - SPECIAL PRECAUTI	ONS	
PRECAUTIONS TO BE TAKEN IN HANDI	LING AND STORAGE	Keep dry and container closed when not in us
OTHER PRECAUTIONS For Jac	dustrial and must	elelel was
FOr inc	dustrial and muni	icipal use.
Shipping Name: DOT Compound Boile	er Cleansing, Pre	reserving Scale Removing, dry - NOT RESTRICTE
IATA	-0,	
		Prepared By W. M. Morris
•		Date: 5/78 (Rev. 6/84)
		Jac. 3/10

I